

Programmable Circle Welders



The **CWP-5 Programmable Circle Welder (CWP-1500)** is designed for single or multi-pass welding of couplings or nozzles utilizing MIG or Flux Core process capable of welding 1-12" (25-305 mm) diameters. This machine uses a microprocessor to control the rise and fall through encoder position.

The **CWP-5AX Programmable Circle Welder (CWP-1560)** is designed for single or multi-pass welding of couplings or nozzles utilizing Sub-Arc, MIG or Flux Core process capable of welding 1-12" (25-305 mm) diameters. This machine uses a microprocessor to control the rise and fall through encoder position.

The **CWP-7 Programmable Circle Welder (CWP-1700)** is equipped for MIG, Flux Core or Sub-Arc welding on vessels and domed heads. The CW-7 has a working range of 6-24" (152-610 mm) O.D. nozzles with no cable wrap up for multi-pass welding. This machine uses a microprocessor to control the rise and fall through encoder position.

These units are capable of using welding wire sizes from .035-3/32" (.8-2.4 mm). Please refer to the chart (on pg. 7) for additional information.



The **CWP-18 Programmable Circle Welder (CWP-1800-SA)** is designed for single or multi-pass welding of couplings or nozzles into vessels or domed heads utilizing Sub-Arc, MIG or Flux Core process with gas shielding. The CWP-18 mounts on a 3 jaw chuck for welding diameters of 10-50" (254-1270 mm) O.D. This machine uses a microprocessor to control the rise and fall through encoder positioning. Photo shown with optional Flux Recovery System installed.



The **CWP-11 Programmable Circle Welder** (**CWP-1100**) is designed for welding of nozzles into vessels utilizing Sub-Arc, MIG or Flux Cored Process. The CWP-11 mounts on a 3-Jaw Chuck for welding diameter 6-50" (152-1270 mm) O.D. The machine uses a microprocessor to control the rise and fall through encoder positioning. Photo shown with optional Flux Recovery System installed.



Programmable Circle Welders

Model	Process Capabilities	Welding Diameter	Welding Wire Size	Rotation Speeds	Rise / Fall	Rating amps	Standard Equipment
CWP-5 CWP-1500	MIG/MAG, FCAW	1-12" (25- 305mm)	.035-1/16" (.8-1.6mm)	.5-6.0 rpm	CNC Controlled	300 amps 100% duty cycle	Burn back control, horizon- tal and vertical adjustment gun & cable
CWP-5AX CWP-1560	MIG/MAG, FCAW, SAW	1-12" (25- 305mm)	.035-3/32" (.8-2.4mm)	.5-6.0 rpm	CNC Controlled	500 amps 100% duty cycle	Same as CW-5 plus: meter kit, torch angle adjuster, flux hopper, nozzle & cone.
CWP-7 CWP-1700	MIG/MAG, FCAW, SAW	6-24" (150- 610mm)	.035-3/32" (.8-2.4mm)	.2-2.2 rpm	CNC Controlled	500 amps 100% duty cycle	Burn back control, horizon- tal and vertical adjustment gun & cable.
CWP-11 CWP-1100	MIG/MAG, FCAW, SAW	10-50" (254- 1270mm)	Solid Wire .035-3/32" (.8-3.0mm) Flux Cored Wire .068120" (1.7-3.0mm)	.2-2.2 rpm	CNC Controlled	500 amp CO ₂ 400 amp mixed gasses 60% duty cycle	Burn back control, horizon- tal and vertical adjustment gun & cable.
CWP-18 CWP-1800	SAW	10-50" (254- 1270mm)	Solid Wire 3/32-7/32" (2.4-5.6mm)	.2-2.2 rpm	CNC Controlled	1200 amps	Burn back control, horizon- tal and vertical adjustment gun & cable.

Capabilities

Saddle Welds	Partial Offset Saddle Welds	Full Offset Saddle Welds	
Programmable or Standard	Programmable Only	Programmable or Standard with Hillside Kit	
Axes In-line: When the axes of the tube are in-line with each other, a standard machine with a mechanical cam will provide two equal rise and fall motions to follow the contour of the weld.	Axes offset, small tube still passes through the center of main tube: When the axes of the tubes are offset, but the small tube still passes over the center-line of the large tube, the contour of the weld is one small rise and fall and one larger rise and fall. The tube diameter and the off-set distance are entered into a program. The resulting contoured travel is calculated as part of the program. All motion is motorized and encoder controlled.	Axes offset, small tube completely off center of main tube axes: When the axes of the tubes are offset so far that the small tube is completely outside the main tubes center-line. A standard machine with a hillside adapter kit will produce the single rise and fall motion required to follow the contour of the weld.	