


PLASMA CUTTING

ERGOCUT S 25

trafimet
distribution

trafimet
welding & cutting



V peak	500	5 bar	95 l/min
X 60%	25A	6÷8 mm	

CODE	↔	
PA0411	4 m / 12.5'	Direct 2 wires




Circle Cutting Attachment




CV0025

FLOW METER

Included in the box



test the airflow of your torch before use



Direct 2 Wires



EN 60974-7



PR0110



PR0106



PE0106




PE0106



Ø mm	Ø in	Cu	⏏
0,6	.023	PD0116-06	20 A
0,8	.030	PD0116-08	30 A
0,9	.035	PD0116-09	40 A



Ø mm	Ø in	Cu	⏏
0,65	.025	PD0103-65	20 A
0,9	.035	PD0103-09	40 A



TORCH WITHOUT SAFETY TRIGGER



TP0080




PF0125

PC0116

no ring



CV0024



STANDARD